

RESERVE STUDY

for the

Pacific Point
HOMEOWNERS ASSOCIATION

Date Prepared: 07/13/05 *for Fiscal Year 2005*

Prepared By:

John D. Beatty & Company

111 Deerwood Road, Suite 380

San Ramon, CA 94583

(925) 831-1803

Fax (925) 831-2493

Contents

<u>Reserve Study</u>	<u>Pages</u>
Introduction	1
Findings and Disclosures	2
Projected Expenditures	3 - 14
Funding Plan	15 - 18
Component Quantification	19 - 21
Accrued Liability	22 - 24

Reserve Study

This report documents the results of a reserve study performed by John D. Beatty & Company for the Pacific Point Homeowners Association in Pacifica, California. It provides an analysis of the repair and replacement requirements for the association's major components and recommends a funding plan to meet those obligations. This study was performed in compliance with California Civil Code sections 1365 and 1365.5. The intent of this legislation is to insure that associations maintain a plan to meet all future obligations for major component maintenance. The essential elements of this legislation are:

1. Identification of the major components which the association is obligated to maintain
2. Current estimate of the useful life of each component
3. Current estimate of the remaining life of each component
4. Current estimate of the replacement cost of each component
5. Current estimate of the total annual contribution necessary to maintain the major components
6. Current estimate of the amount of cash reserves necessary to maintain the major components
7. Disclosure of the current amount of accumulated cash reserves actually funded
8. Disclosure of the percentage of reserves actually funded
9. Disclosure of any determined or anticipated special assessments
10. A general statement of methodology

SCOPE

This study is aligned with the association's fiscal year and establishes January 1, 2005 through December 31, 2044 as the period of time for which reserve expenditures and reserve fund balances are projected.

METHODOLOGY

A cash flow methodology was used to determine the annual reserve contribution. The underlying premise of this reserve funding approach is to establish a contribution level that will allow the association to maintain a positive balance in the reserve fund while meeting all anticipated maintenance obligations. The cash flow method allows the association to achieve this goal without the unnecessary overfunding of reserves. Also, as the interest earned on the reserve fund will not totally offset inflation, projections were made using the current inflation factor and an average interest rate on fully insured certificates of deposit.

In preparing this study, a comprehensive list of major components was developed and information was compiled on the type, number, age and cost of each of these components. In gathering this data, certain assumptions were made about costs, conditions, and future events and circumstances that may occur. Some assumptions inevitably will not materialize and unanticipated events and circumstances may occur subsequent to the date of this report. Therefore, the actual replacement costs and remaining lives may vary from this report and the variations could be material. All life expectancies were based on reasonable industry experience for equipment and material and, unless specifically noted, all components were in a reasonable and ordinary condition.

This study was limited to a visual inspection of the property and as such did not disturb the major components. Therefore, all common areas for which there is no access without defacement are specifically omitted. However, if sufficient historical data were available that would allow a reasonable projection of future expenditures for any unobservable components e.g., plumbing or electrical wiring, those components could be included in this report.

Since no destructive testing was undertaken, this study does not purport to address any latent and/or patent defects, nor does it address any life expectancies that are abnormally short due to either improper design or installation, or to subsequent improper maintenance. It is assumed that all components are to be reasonably maintained for the remainder of their life expectancy.

For a component to be included in this study, the following criteria must be met:

1. The maintenance of the component is the responsibility of the association;
2. The maintenance of the component is not included in the annual operating budget;
3. The estimated useful life of the component is greater than one year; and
4. The estimated remaining life of the component is less than 30 years.

This study is intended to reflect the estimated replacement cost of the components and is not intended to project the actual cost of the work when performed. This limitation is necessary, as it is virtually impossible to predict with any degree of certainty the myriad factors that will impact costs at a future date. Because of this qualification, it is necessary for the results of this study to be reviewed annually to reflect any meaningful changes in use or significant increases in labor and/or materials costs.

The funding for this study has a threshold margin of 10%. This means that the projected ending balance for each fiscal year is at least 10% of the projected expenditures for the same year. This margin provides for any unforeseen or out of the ordinary repair or replacement expense. Additionally, it can be used in subsequent years as a source of funds for reallocation of the life cycles should the aging of any components be abnormally accelerated.

FINDINGS

The findings of this study indicate that it will be necessary to adjust the annual reserve contribution as indicated on pages 15, 16, 17 and 18 of this report in order to meet projected expenditures and keep pace with inflation. For fiscal year 2005 an increase of 0.0% is recommended in the reserve contribution, however it is recommended that the Association implement a special assessment in the amount of \$294,119 in fiscal year 2005 and an additional special assessment of \$392,000 in fiscal year 2006. These findings are based upon the following:

- | | |
|--|-----------|
| 1. Projected reserve fund balance as of January 1, 2005..... | \$60,000 |
| 2. Reserve contribution for fiscal year 2004 | \$164,863 |
| 3. Reserve contribution for fiscal year 2005 | \$164,863 |
| 4. Special Assessment for fiscal year 2005 | \$294,119 |
| 5. Special Assessment for fiscal year 2006 | \$392,000 |
| 6. Assumed annual inflation rate..... | 3.0% |
| 7. All "after tax" interest earned on reserve fund investments will be retained in the reserve fund. | |

DISCLOSURES

This plan provides adequate funds to meet projected expenditures while relying on special assessments in both fiscal years 2005 and 2006, which will require votes of the membership. However, the recommended increase in the regular assessment will not require a vote of the membership. Based on the assumption that the association will fund reserves in accordance with this plan, which includes those increases indicated above, the percent funded was calculated in the following manner:

Accumulated Cash Reserves (Numerator)

Projected reserve fund balance as of January 1, 2005.....\$60,000

Accrued Liability (Denominator)

(Refer to page 24 of this report)

Estimate of the amount of cash necessary to repair, replace, restore
or maintain the association's major components as of January 1, 2005\$1,089,406

Percent Funded.....

6%

Projected Expenditures

Assumed Annual Inflation Rate.....	3.0%	Current Repair Cost	Estimated Usfl Life	Fiscal Year Jan 1	(1) 2005	(2) 2006	(3) 2007	(4) 2008	(5) 2009	(6) 2010	(7) 2011	(8) 2012	(9) 2013	(10) 2014
RESERVE COMPONENTS	%	Repair Replace Cost	Life	Dec 31	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014
BUILDING EXTERIORS:														
1 - Plywood Siding & Trim Paint		59,837	5	2					61,632					71,448
2 - Plywood Siding & Trim Repair	20%	47,689	5	2					49,120					56,944
3 - Staircase Repairs		20,600	5	1				20,600						23,881
4 - Stucco Siding Paint		144,155	10	2					148,480					
5 - Stucco Siding Repair	5%	32,597	10	2					43,875					
6 - Unit Deck Sticks Rebuild		219,493	20	20										
7 - Unit Deck Stacks Rebuild		219,493	20	1				155,812	63,681					
8 - Unit Deck Joist Repairs		28,922	5	1				28,922						33,529
9 - Water Intrusion Contingency		79,825	20	1				26,609	26,608					64,508
10 - Wing Wall Repairs		49,440	3	1				49,440						
11 - Wood Bridgeway Repairs		30,909	10	1				30,909						
BUILDING INTERIORS - CLUBHOUSE:														
12 - Concealed Decay Contingency		21,000	15	1				21,000						
13 - Walls & Ceilings Paint		3,754	7	2				3,866						4,755
CLUBHOUSE DECK SYSTEM:														
14 - Deck Railings Repair		4,297	15	15										
15 - Deck Structure Rebuild		29,000	25	25										
FENCING & WALLS:														
16 - Chain Link Repairs - Tennis Cour	20%	1,680	15	5										1,891
17 - Retaining Walls Repair	25%	2,387	5	3					2,532					2,936
18 - Wood Gates Paint & Repair		2,864	5	2					2,950					3,420
19 - Wrought Iron Paint		1,650	5	2					1,699					1,970
20 - Wrought Iron Repair	10%	3,590	10	6										4,162
FLOOR COVERINGS:														
21 - Recreation Room Carpet Replace		2,507	7	1					2,507					3,084
22 - Wood & Tile Floor Refinish		3,021	7	1					3,021					3,715
FURNISHINGS & APPLIANCES:														
23 - Recreation Room Items		2,652	10	1					2,652					
LANDSCAPING:														
24 - Irrigation Timer Replace		1,167	5	3					1,238					
25 - Irrigation Valves		1,326	2	1					1,407					
26 - Major Tree Maintenance		5,305	3	1					5,305					
LIGHT FIXTURES:														
27 - Garage Lights Replace		3,437	20	5										3,869
28 - Building Lights Interior		424	25	10										554
29 - Exit Lights Replace		191	25	5										215
30 - Ground Lights Replace		3,151	20	5										3,546

Projected Expenditures

Projected Expenditures

Projected Expenditures

Assumed Annual Inflation Rate.....		3.0%	Current Repair/Replace Cost	Estimated Usfl Life	Fiscal Year Jan 1	(11) 2015	(12) 2016	(13) 2017	(14) 2018	(15) 2019	(16) 2020	(17) 2021	(18) 2022	(19) 2023	(20) 2024
RESERVE COMPONENTS		%	Repair Cost	Rmng Life	Dec 31	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024
BUILDING EXTERIORS:															
1 - Plywood Siding & Trim Paint			\$9,837	5	2										
2 - Plywood Siding & Trim Repair	20%		47,689	5	2										
3 - Staircase Repairs			20,600	5	1										
4 - Stucco Siding Paint			144,155	10	2										
5 - Stucco Siding Repair		5%	42,597	10	2										
6 - Unit Deck Stacks Rebuild			219,493	20	20										
7 - Unit Deck Stacks Rebuild			219,493	20	1										
8 - Unit Deck Joist Repairs			28,922	5	1										
9 - Water Intrusion Contingency			79,825	20	1										
10 - Wing Wall Repairs			49,440	3	1										
11 - Wood Bridgeway Repairs			30,900	10	1										
BUILDING INTERIORS - CLUBHOUSE:															
12 - Concealed Decay Contingency			21,000	15	1										
13 - Walls & Ceilings Paint			3,754	7	2										
CLUBHOUSE DECK SYSTEM:															
14 - Deck Railings Repair			4,297	15	15										
15 - Deck Structure Rebuild			29,000	25	25										
FENCING & WALLS:															
16 - Chain Link Repairs - Tennis Cour			1,680	15	5										
17 - Retaining Walls Repair			2,387	5	3										
18 - Wood Gates Paint & Repair			2,864	5	2										
19 - Wrought Iron Paint			1,650	5	2										
20 - Wrought Iron Repair		10%	3,590	10	6										
FLOOR COVERINGS:															
21 - Recreation Room Carpet Replace			2,507	7	1										
22 - Wood & Tile Floor Refinish			3,021	7	1										
FURNISHINGS & APPLIANCES:															
23 - Recreation Room Items			2,652	10	1										
LANDSCAPING:															
24 - Irrigation Timer Replace			1,167	5	3										
25 - Irrigation Valves			1,326	2	1										
26 - Major Tree Maintenance			5,305	3	1										
LIGHT FIXTURES:															
27 - Garage Lights Replace			3,437	20	5										
28 - Building Lights Interior			424	25	10										
29 - Exit Lights Replace			191	25	5										
30 - Ground Lights Replace			3,151	20	5										

Projected Expenditures

Assumed Annual Inflation Rate.....	3.0%	Current Repair/Replace Cost	Estimated Usfl Life	Fiscal Year Jan 1.....	(11) 2015	(12) 2016	(13) 2017	(14) 2018	(15) 2019	(16) 2020	(17) 2021	(18) 2022	(19) 2023	(20) 2024
RESERVE COMPONENTS .%				2015 Dcc 31	2016	2016	2017	2018	2019	2020	2021	2022	2023	2024
LIGHT FIXTURES - CONTINUED:														
31 - Pole Lights - Fixture Replace		6,684	20	5										
32 - Unit Entry Lights Replace		9,877	20	5										
33 - Unit Patio & Deck Lights Replace		5,644	20	5										
34 - Walkway Lights Replace		5,952	20	5										
MECHANICAL SYSTEMS - GARAGE DOORS:														
35 - Garage Doors Replace - Doubles		40,314	20	5										
36 - Garage Doors Replace - Singles		1,008	20	5										
MECHANICAL SYSTEMS-HVAC:														
37 - Forced Air Furnace Replace		1,591	20	10										
MECHANICAL SYSTEMS-WATER:														
38 - Circulation Pumps Replace		1,500	10	3										
39 - Boilers Replace		12,000	15	8										
40 - Circulation Pumps Replace		3,000	10	4										
41 - Boilers Replace		24,000	15	9										
42 - Circulation Pumps Replace		7,500	10	5										
43 - Boilers Replace		60,000	15	10										
44 - Water Valve Replacements (2)		3,183	30	1										
45 - Water Valve Replacements (2)		3,183	30	2										
46 - Water Valve Replacements (2)		3,183	30	3										
47 - Water Valve Replacements (2)		3,183	30	4										
48 - Water Valve Replacements (1)		1,591	30	5										
PAVED SURFACES:														
49 - Asphalt Major Repair	33%	89,752	25	12										
50 - Asphalt Minor Repair	20%	27,197	10	7										
51 - Asphalt Sealcoat & Stripe		10,305	5	2										
52 - Concrete Walkway Repairs		1,591	5	2										
53 - Tennis Court Colorcoat		8,784	7	2										
54 - Tennis Court Resurfacing		17,208	21	9										
RECREATION FACILITIES:														
55 - Tennis Court Net Replace		451	5	3										
56 - Tot Lot Fixtures		4,244	20	5										
ROOFING SYSTEM:														
BUILDING #1 - 50115														
57 - Built-Up Roofing Replace		36,075	20	12										
58 - Composition Shingles Replace		6,807	25	17										
BUILDING #2 - 50111														
59 - Built-Up Roofing Replace		36,075	20	12										
60 - Composition Shingles Replace		6,807	25	17										

Projected Expenditures

Assumed Annual Inflation Rate.....		3.0%	Current Repair Cost	Estimated Usfl Life	Fiscal Year Jan 1	(11) 2015	(12) 2016	(13) 2017	(14) 2018	(15) 2019	(16) 2020	(17) 2021	(18) 2022	(19) 2023	(20) 2024	
RESERVE COMPONENTS %			Repair Replace Cost	Estimated Life	Dec 31											
BUILDING #3 - 5009			36,075	20	12											
61 - Built-Up Roofing Replace		6,807	25	17												
62 - Composition Shingles Replace						49,937										
BUILDING #4 - 5007			36,075	20	12											
63 - Built-Up Roofing Replace		6,807	25	17												
64 - Composition Shingles Replace						49,937										
BUILDING #5 - 5005			36,075	20	12											
65 - Built-Up Roofing Replace		6,807	25	17												
66 - Composition Shingles Replace						49,937										
BUILDING #6 - 5017			36,075	20	12											
67 - Built-Up Roofing Replace		6,807	25	17												
68 - Composition Shingles Replace						49,937										
BUILDING #7 - 5011			36,075	20	12											
69 - Built-Up Roofing Replace		6,807	25	17												
70 - Composition Shingles Replace						49,937										
BUILDING #8 - 5003			53,043	20	3											
71 - Built-Up Roofing Replace		6,608	25	1												
72 - Composition Shingles Replace						49,937										
ROOFING SYSTEM - ALL BUILDINGS:																
ROOFING SYSTEM:																
73 - Chimney Caps Replace		20,188	20	1												
74 - Chimney Caps Replace		20,188	20	2												
75 - Gutters & Downspouts Replace		2,575	2	1												
76 - Spark Arrestors Replace		9,085	25	1												
77 - Spark Arrestors Replace		9,085	25	2												
ROOFING SYSTEM - GARAGES:																
78 - Composition Shingles Replace		51,936	25	12												
MISCELLANEOUS:																
79 - Mailboxes Replace		10,397	10	5												
CONSTRUCTION LOAN:																
80 - Amortization Payment Schedule		173,782	1	1												
UNSCHEDEDLED:																
TOTAL EXPENDITURES			2,046,939													
			138,801													
			999,151													
			114,710													
			28,350													
			72,495													
			245,691													
			357,372													
			33,569													
			127,599													
			416,420													

Projected Expenditures

RESERVE COMPONENTS	Assumed Annual Inflation Rate.....	3.0%	Repair %	Current Repair/Replace Cost	Estimated Usfl Life	Fiscal Year Jan 1 ... Dec 31	(21) 2025	(22) 2026	(23) 2027	(24) 2028	(25) 2029	(26) 2030	(27) 2031	(28) 2032	(29) 2033	(30) 2034	
BUILDING EXTERIORS:																	
1 - Plywood Siding & Trim Paint				59,837	5	2											
2 - Plywood Siding & Trim Repair	20%			47,689	5	2											
3 - Staircase Repairs				20,600	5	1											
4 - Stucco Siding Paint				144,155	10	2											
5 - Stucco Siding Repair	5%			42,597	10	2											
6 - Unit Deck Stacks Rebuild				219,493	20	20											
7 - Unit Deck Stacks Rebuild				219,493	20	1											
8 - Unit Deck Joist Repairs				28,922	5	1											
9 - Water Intrusion Contingency				79,825	20	1											
10 - Wing Wall Repairs				49,440	3	1											
11 - Wood Bridgeway Repairs				30,900	10	1											
BUILDING INTERIORS - CLUBHOUSE:																	
12 - Concealed Decay Contingency				21,000	15	1											
13 - Walls & Ceilings Paint				3,754	7	2											
CLUBHOUSE DECK SYSTEM:																	
14 - Deck Railings Repair				4,297	15	15											
15 - Deck Structure Rebuild				29,000	25	25											
FENCING & WALLS:																	
16 - Chain Link Repairs - Tennis Cour	20%			1,680	15	5											
17 - Retaining Walls Repair	25%			2,387	5	3											
18 - Wood Gates Paint & Repair				2,864	5	2											
19 - Wrought Iron Paint				1,650	5	2											
20 - Wrought Iron Repair	10%			3,590	10	6											
FLOOR COVERINGS:																	
21 - Recreation Room Carpet Replace				2,507	7	1											
22 - Wood & Tile Floor Refinish				3,021	7	1											
FURNISHINGS & APPLIANCES:																	
23 - Recreation Room Items				2,652	10	1											
LANDSCAPING:																	
24 - Irrigation Timer Replace				1,167	5	3											
25 - Irrigation Valves				1,326	2	1											
26 - Major Tree Maintenance				5,305	3	1											
LIGHT FIXTURES:																	
27 - Garage Lights Replace				3,437	20	5											
28 - Building Lights Interior				424	25	10											
29 - Exit Lights Replace				191	25	5											
30 - Ground Lights Replace				3,151	20	5											

Projected Expenditures

RESERVE COMPONENTS	Assumed Annual Inflation Rate.....	3.0%	Current Repair/Replace Cost	Estimated Usfl Life	Fiscal Year Jan 1 ... Dec 31 ...	(21) 2025	(22) 2026	(23) 2027	(24) 2028	(25) 2029	(26) 2030	(27) 2031	(28) 2032	(29) 2033	(30) 2034
LIGHT FIXTURES - CONTINUED:															
31 - Pole Lights - Fixture Replace	6,684	20	5												
32 - Unit Entry Lights Replace	9,877	20	5												
33 - Unit Patio & Deck Lights Replace	5,644	20	5												
34 - Walkway Lights Replace	5,952	20	5												
MECHANICAL SYSTEMS - GARAGE DOORS:															
35 - Garage Doors Replace - Doubles	40,314	20	5												
36 - Garage Doors Replace - Singles	1,008	20	5												
MECHANICAL SYSTEMS-HVAC:															
37 - Forced Air Furnace Replace	1,591	20	10												
MECHANICAL SYSTEMS-WATER:															
38 - Circulation Pumps Replace	1,500	10	3												
39 - Boilers Replace	12,000	15	8												
40 - Circulation Pumps Replace	3,000	10	4												
41 - Boilers Replace	24,000	15	9												
42 - Circulation Pumps Replace	7,500	10	5												
43 - Boilers Replace	60,000	15	10												
44 - Water Valve Replacements (2)	3,183	30	1												
45 - Water Valve Replacements (2)	3,183	30	2												
46 - Water Valve Replacements (2)	3,183	30	3												
47 - Water Valve Replacements (2)	3,183	30	4												
48 - Water Valve Replacements (1)	1,591	30	5												
PAVED SURFACES:															
49 - Asphalt Major Repair	33%	89,752	25	12											
50 - Asphalt Minor Repair	20%	27,197	10	7											
51 - Asphalt Sealcoat & Stripe		10,905	5	2											
52 - Concrete Walkway Repairs		1,591	5	2											
53 - Tennis Court Colorcoat		8,784	7	2											
54 - Tennis Court Resurfacing		17,208	21	9											
RECREATION FACILITIES:															
55 - Tennis Court Net Replace		451	5	3											
56 - Tot Lot Fixtures		4,244	20	5											
ROOFING SYSTEM:															
BUILDING #1 - 5015		36,075	20	12											
57 - Built-Up Roofing Replace		6,807	25	17											
58 - Composition Shingles Replace															
BUILDING #2 - 5011		36,075	20	12											
59 - Built-Up Roofing Replace		6,807	25	17											
60 - Composition Shingles Replace															

7/13/2005

Page 10

Pacific Point Jan 2005 RSb.xls

Projected Expenditures

Assumed Annual Inflation Rate.....	3.0%	Repair %	Current Repair/Replace Cost	Estimated Usfl Life	Fiscal Year Jan 1	(21)	(22)	(23)	(24)	(25)	(26)	(27)	(28)	(29)	(30)
RESERVE COMPONENTS	%			Life	Dec 31	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034
BUILDING #3 - 50019															
61 - Built-Up Roofing Replace			36,075	20	12										
62 - Composition Shingles Replace			6,807	25	17										
BUILDING #4 - 50017															
63 - Built-Up Roofing Replace			36,075	20	12										
64 - Composition Shingles Replace			6,807	25	17										
BUILDING #5 - 50015															
65 - Built-Up Roofing Replace			36,075	20	12										
66 - Composition Shingles Replace			6,807	25	17										
BUILDING #6 - 50117															
67 - Built-Up Roofing Replace			36,075	20	12										
68 - Composition Shingles Replace			6,807	25	17										
BUILDING #7 - 50011															
69 - Built-Up Roofing Replace			36,075	20	12										
70 - Composition Shingles Replace			6,807	25	17										
BUILDING #8 - 50013															
71 - Built-Up Roofing Replace			53,043	20	3										
72 - Composition Shingles Replace			6,608	25	1										
ROOFING SYSTEM - ALL BUILDINGS:															
ROOFING SYSTEM:															
73 - Chimney Caps Replace			20,188	20	1										
74 - Chimney Caps Replace			20,188	20	2										
75 - Gutters & Downspouts Replace			2,575	2	1										
76 - Spark Arrestors Replace			9,085	25	1										
77 - Spark Arrestors Replace			9,085	25	2										
ROOFING SYSTEM - GARAGES:															
78 - Composition Shingles Replace			51,936	25	12										
MISCELLANEOUS:															
79 - Mailboxes Replace			10,397	10	5										
CONSTRUCTION LOAN:															
80 - Amortization Payment Schedule UNSCHEDULED.....	5%		173,782	1	1										
TOTAL EXPENDITURES															
						29,449	30,332	31,242	32,179	33,145	34,139	35,163	36,218	37,305	38,424
						763,600	759,101	197,918	85,466	532,914	178,202	390,396	166,718	58,879	122,847

Projected Expenditures

Assumed Annual Inflation Rate.....		3.0%	Repair %	Current Repair/Replace Cost	Estimated Usfl Life	Fiscal Year Jan 1	(31) 2035	(33) 2036	(34) 2038	(35) 2039	(36) 2040	(37) 2041	(38) 2042	(39) 2043	(40) 2044
RESERVE COMPONENTS		%													
BUILDING EXTERIORS:															
1 - Plywood Siding & Trim Paint	\$9,837	5	2				149,597								173,423
2 - Plywood Siding & Trim Repair	47,689	5	2				119,227								138,217
3 - Staircase Repairs	20,600	5	1				50,002								57,966
4 - Stucco Siding Paint	144,155	10	2				360,400								
5 - Stucco Siding Repair	42,597	10	2				106,495								695,140
6 - Unit Deck Stacks Rebuild	219,493	20	20												
7 - Unit Deck Stacks Rebuild	219,493	20	1				70,202								
8 - Unit Deck Joist Repairs	28,922	5	1												
9 - Water Intrusion Contingency	79,825	20	1												156,578
10 - Wing Wall Repairs	49,440	3	1				120,004								
11 - Wood Bridgeway Repairs	30,900	10	1				75,002								
BUILDING INTERIORS - CLUBHOUSE:															
12 - Concealed Decay Contingency	21,000	15	1				50,973								10,879
13 - Walls & Ceilings Paint	3,754	7	2												
CLUBHOUSE DECK SYSTEM:															
14 - Deck Railings Repair	4,297	15	15												
15 - Deck Structure Rebuild	29,000	25	25												
FENCING & WALLS:															
16 - Chain Link Repairs - Tennis Court	1,680	15	5												
17 - Retaining Walls Repair	2,387	5	3												
18 - Wod Gates Paint & Repair	2,864	5	2												
19 - Wrought Iron Paint	1,650	5	2												
20 - Wrought Iron Repair	10%	3,590	10	6											
FLOOR COVERINGS:															
21 - Recreation Room Carpet Replace	2,507	7	1												7,055
22 - Wood & Tile Floor Refinish	3,021	7	1												8,501
FURNISHINGS & APPLIANCES:															
23 - Recreation Room Items	2,652	10	1												
LANDSCAPING:															
24 - Irrigation Timer Replace	1,167	5	3												
25 - Irrigation Valves	1,326	2	1												
26 - Major Tree Maintenance	5,305	3	1												
LIGHT FIXTURES:															
27 - Garage Lights Replace	3,437	20	5												
28 - Building Lights Interior	424	25	10												
29 - Exit Lights Replace	191	25	5												
30 - Ground Lights Replace	3,151	20	5												

Projected Expenditures

RESERVE COMPONENTS	%	Repair Cost	Current Repair/Replace Cost	Estimated Usfl Life	Fiscal Year Jan 1 ... Dec 31	(31) 2035	(32) 2036	(33) 2037	(34) 2038	(35) 2039	(36) 2040	(37) 2041	(38) 2042	(39) 2043	(40) 2044
LIGHT FIXTURES - CONTINUED:															
31 - Pole Lights - Fixture Replace		6,684	20	5											
32 - Unit Entry Lights Replace		9,877	20	5											
33 - Unit Patio & Deck Lights Replace		5,644	20	5											
34 - Walkway Lights Replace		5,952	20	5											
MECHANICAL SYSTEMS - GARAGE DOORS:															
35 - Garage Doors Replace - Doubles		40,314	20	5											
36 - Garage Doors Replace - Singles		1,008	20	5											
MECHANICAL SYSTEMS-HVAC:															
37 - Forced Air Furnace Replace		1,591	20	10											
MECHANICAL SYSTEMS-WATER:															
38 - Circulation Pumps Replace		1,500	10	3											
39 - Boilers Replace		12,000	15	8											
40 - Circulation Pumps Replace		3,000	10	4											
41 - Boilers Replace		24,000	15	9											
42 - Circulation Pumps Replace		7,500	10	5											
43 - Boilers Replace		60,000	15	10											
44 - Water Valve Replacements (2)		3,183	30	1											
45 - Water Valve Replacements (2)		3,183	30	2											
46 - Water Valve Replacements (2)		3,183	30	3											
47 - Water Valve Replacements (2)		3,183	30	4											
48 - Water Valve Replacements (1)		1,591	30	5											
PAVED SURFACES:															
49 - Asphalt Major Repair	33%	89,752	25	12											
50 - Asphalt Minor Repair	20%	27,197	10	7											
51 - Asphalt Sealcoat & Stripe		10,905	5	2											
52 - Concrete Walkway Repairs		1,591	5	2											
53 - Tennis Court Colorcoat		8,784	7	2											
54 - Tennis Court Resurfacing		17,208	21	9											
55 - Tennis Court Net Replace		451	5	3											
56 - Tot Lot Fixtures		4,244	20	5											
ROOFING SYSTEM:															
BUILDING #1 - 5015		36,075	20	12											
57 - Built-Up Roofing Replace		6,807	25	17											
58 - Composition Shingles Replace															
BUILDING #2 - 5011		36,075	20	12											
59 - Built-Up Roofing Replace		6,807	25	17											
60 - Composition Shingles Replace															

Projected Expenditures

Funding Plan

Projected Cash Balance

Fiscal Year	(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)
Jan 1	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014
Dec 31	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014
BEGINNING BALANCE										
EXPENDITURES (inflated \$)	3.0%	454,108	522,123	161,605	132,464	137,173	80,474	270,673	46,536	93,680
RESERVE CONTRIBUTION										
Per Unit Per Month (98 units)										
Percentage Increase to Reserves										
Percentage Increase to Total Assessment										
SPECIAL ASSESSMENTS										
INTEREST										
ENDING BALANCE										

652,106

Funding Plan


Projected Cash Balance										
Fiscal Year	(11)	(12)	(13)	(14)	(15)	(16)	(17)	(18)	(19)	(20)
Jan 1	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024
Dec 31	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024
BEGINNING BALANCE	652,106	798,476	103,307	292,379	572,482	813,385	885,020	852,560	1,142,593	1,343,466
EXPENDITURES (inflated \$)	3.0%	138,801	999,151	114,710	28,350	72,495	245,691	352,372	33,569	127,599
RESERVE CONTRIBUTION										
Per Unit Per Month (98 units)										
Percentage Increase to Reserves										
SPECIAL ASSESSMENTS										
INTEREST										
ENDING BALANCE										

Funding Plan

	(21)	(22)	(23)	(24)	(25)	(26)	(27)	(28)	(29)	(30)
Fiscal Year	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034
Jan 1	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034
Dec 31										
BEGINNING BALANCE	1,258,542	826,331	396,816	529,511	779,083	746,070	699,079	879,031	1,171,795	1,405,856
EXPENDITURES (inflated \$)	3.0%	763,600	759,101	197,918	85,466	532,914	178,202	390,396	166,718	58,879
RESERVE CONTRIBUTION										
Per Unit Per Month (98 units)										
Percentage Increase to Reserves										
SPECIAL ASSESSMENTS	0.4	0.4	0.4	0.4	0.4	0.4	0.4	0.4	0.4	0.4
INTEREST	1.0%	10,373	6,085	4,609	6,510	6,782	6,617	7,190	7,851	10,203
ENDING BALANCE	826,331	396,816	529,511	779,083	584,021	746,070	699,079	879,031	1,171,795	1,405,856

Funding Plan

1,323,916



Projected Cash Balance

Fiscal Year	(31)	(32)	(33)	(34)	(35)	(36)	(37)	(38)	(39)	(40)
Jan 1	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044
Dec 31	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044
BEGINNING BALANCE	1,405,856	1,323,916	222,738	504,084	659,890	911,121	1,070,468	336,650	610,886	851,043
EXPENDITURES (inflated \$)	3.0%	442,267	1,458,304	74,404	204,846	114,191	210,887	1,103,982	96,452	135,924
RESERVE CONTRIBUTION	346,746	349,430	352,335	354,860	357,607	360,375	363,164	365,975	368,807	371,662
Per Unit Per Month (98 units)										
Percentage Increase to Reserves										
0.8	0.8	0.8	0.8	0.8	0.8	0.8	0.8	0.8	0.8	0.8
0.4	0.4	0.4	0.4	0.4	0.4	0.4	0.4	0.4	0.4	0.4
Percentage Increase to Total Assessment										
0	0	0	0	0	0	0	0	0	0	0
SPECIAL ASSESSMENTS	0.4%	13,581	7,695	3,616	5,791	7,816	9,859	7,001	4,714	7,273
INTEREST										
1.0%	1,323,916	222,738	504,084	659,890	911,121	1,070,468	336,650	610,886	851,043	117,345
ENDING BALANCE										

Component Quantification

Assumed Annual Inflation Rate.....	3.0%	Repair %	Current Repair/Cost	Estimated Usfl Life	Rmng Life	Quantity	Unit of Measurement	Unit Cost	Notes
RESERVE COMPONENTS									
1 - Plywood Siding & Trim Paint		59,837	5	2	44,990 square feet	1.33	All notes to accompany final report pending further discussions and potential revisions to		
2 - Plywood Siding & Trim Repair	20%	47,689	5	2	44,990 square feet	5.30	this preliminary report submitted to the current management team on 11/11/04.		
3 - Staircase Repairs		20,600	5	1	4 locations	5,150.00			
4 - Stucco Siding Paint		144,155	10	2	118,160 square feet	1.22			
5 - Stucco Siding Repair		42,597	10	2	118,160 square feet	.721			
6 - Unit Deck Stacks Rebuild	5%	219,493	20	20	1 fund	219,493.00			
7 - Unit Deck Stacks Rebuild		219,493	20	1	1 fund	219,493.00			
8 - Unit Deck lost Repairs		28,922	5	1	18 locations	1,606.80			
9 - Water Intrusion Contingency		79,825	20	1	1 fund	79,825.00			
10 - Wing Wall Repairs		49,440	3	1	8 buildings	6,180.00			
11 - Wood Bridgeway Repairs		30,900	10	1	2 locations	15,450.00			
BUILDING INTERIORS - CLUBHOUSE:									
12 - Concealed Decay Contingency		21,000	15	1	1 bid	21,000.00			
13 - Walls & Ceilings Paint		3,754	7	2	5,440 square feet	0.69			
CLUBHOUSE DECK SYSTEM:									
14 - Deck Railings Repair		4,297	15	15	45 linear feet	95.48			
15 - Deck Structure Rebuild		29,000	25	25	1 bid	29,000.00			
FENCING & WALLS:									
16 - Chain Link Repairs - Tennis Cour	20%	1,680	15	5	360 linear feet	23.34			
17 - Retaining Walls Repair	25%	2,387	5	3	90 linear feet	106.09			
18 - Wood Gates Paint & Repair		2,864	5	2	6 gates	477.41			
19 - Wrought Iron Paint		1,650	5	2	1,410 linear feet	1.17			
20 - Wrought Iron Repair	10%	3,590	10	6	1,410 linear feet	25.46			
FLOOR COVERINGS:									
21 - Recreation Room Carpet Replace		2,507	7	1	630 square feet	3.98			
22 - Wood & Tie Floor Refinish		3,021	7	1	950 square feet	3.18			
FURNISHINGS & APPLIANCES:									
23 - Recreation Room Items		2,652	10.	1	1 fund	2,652.25			
LANDSCAPING:									
24 - Irrigation Timer Replace		1,167	5	3	1 timer	1,166.99			
25 - Irrigation Valves		1,326	2	1	5 valves	265.23			
26 - Major Tree Maintenance		5,305	3	1	1 fund	5,304.50			
LIGHT FIXTURES:									
27 - Garage Lights Replace		3,437	20	5	24 fixtures	143.22			
28 - Building Lights Interior		424	25	10	4 fixtures	106.09			
29 - Exit Lights Replace		191	25	5	2 fixtures	95.48			
30 - Ground Lights Replace		3,151	20	5	27 fixtures	116.70			

Component Quantification

Assumed Annual Inflation Rate..... 3.0%

RESERVE COMPONENTS	Repair %	Current Cost	Estimated Usfl Life	Rmng Life	Quantity	Unit Measurement	Unit Cost	Notes
LIGHT FIXTURES - CONTINUED:								
31 - Pole Lights - Fixture Replace		6,684	20	5	21	Fixtures	318.27	
32 - Unit Entry Lights Replace		9,877	20	5	98	fixtures	100.79	
33 - Unit Patio & Deck Lights Replace		5,644	20	5	56	fixtures	100.79	
34 - Walkway Lights Replace		5,952	20	5	51	fixtures	116.70	
MECHANICAL SYSTEMS - GARAGE DOORS:								
35 - Garage Doors Replace - Doubles		40,314	20	5	20	doors	2,015.71	
36 - Garage Doors Replace - Singles		1,008	20	5	1	door	1,007.86	
MECHANICAL SYSTEMS-HVAC:								
37 - Forced Air Furnace Replace		1,591	20	10	1	unit	1,591.35	
MECHANICAL SYSTEMS-WATER:								
38 - Circulation Pumps Replace		1,500	10	3	1	pump	1,500.00	Information in this section is based on limited information from various vendors. All recommendations are estimates only.
39 - Boilers Replace		12,000	15	8	1	boilers	12,000.00	
40 - Circulation Pumps Replace		3,000	10	4	2	pumps	1,500.00	
41 - Boilers Replace		24,000	15	9	2	boilers	12,000.00	
42 - Circulation Pumps Replace		7,500	10	5	5	pumps	1,500.00	
43 - Boilers Replace		60,000	15	10	5	boilers	12,000.00	
44 - Water Valve Replacements (2)		3,183	30	1	2	locations	1,591.35	
45 - Water Valve Replacements (2)		3,183	30	2	2	locations	1,591.35	
46 - Water Valve Replacements (2)		3,183	30	3	2	locations	1,591.35	
47 - Water Valve Replacements (2)		3,183	30	4	2	locations	1,591.35	
48 - Water Valve Replacements (1)		1,591	30	5	1	location	1,591.35	Information in this section is based on limited information from various vendors. All recommendations are estimates only.
PAVED SURFACES:								
49 - Asphalt Major Repair	33%	89,752	25	12	64,145	square feet	4.24	
50 - Asphalt Minor Repair	20%	27,197	10	7	64,145	square feet	2.12	
51 - Asphalt Sealcoat & Stripe		10,905	5	2	64,145	square feet	0.17	
52 - Concrete Walkway Repairs		1,591	5	2	1	fund	1,591.35	
53 - Tennis Court Colorcoat		8,784	7	2	7,200	square feet	1.22	
54 - Tennis Court Resurfacing		17,208	21	9	7,200	square feet	2.39	
RECREATION FACILITIES:								
55 - Tennis Court Net Replace		451	5	3	1	net	450.88	
56 - Tot Lot Fixtures		4,244	20	5	2	fixtures	2,121.80	
ROOFING SYSTEM:								
57 - Built-Up Roofing Replace		36,075	20	12	1	contract	36,075.26	
58 - Composition Shingles Replace		6,807	25	17	1	contract	6,806.65	

Component Quantification

Assumed Annual Inflation Rate.....	3.0%	Repair %	Repair Cost	Current Repair/Replace	Estimated Usfl Life	Rmng Life	Quantity	Unit of Measurement	Unit Cost	Notes
RESERVE COMPONENTS										
BUILDING #2 - 5011				36,075	20	12	1 contract	36,075.26		
59 - Built-Up Roofing Replace			6,807	25	17	1 contract	6,806.65			
60 - Composition Shingles Replace										
BUILDING #3 - 5009				36,075	20	12	1 contract	36,075.26		
61 - Built-Up Roofing Replace			6,807	25	17	1 contract	6,806.65			
62 - Composition Shingles Replace										
BUILDING #4 - 5007				36,075	20	12	1 contract	36,075.26		
63 - Built-Up Roofing Replace			6,807	25	17	1 contract	6,806.65			
64 - Composition Shingles Replace										
BUILDING #5 - 5015				36,075	20	12	1 contract	36,075.26		
65 - Built-Up Roofing Replace			6,807	25	17	1 contract	6,806.65			
66 - Composition Shingles Replace										
BUILDING #6 - 5017				36,075	20	12	1 contract	36,075.26		
67 - Built-Up Roofing Replace			6,807	25	17	1 contract	6,806.65			
68 - Composition Shingles Replace										
BUILDING #7 - 5001				36,075	20	12	1 contract	36,075.26		
69 - Built-Up Roofing Replace			6,807	25	17	1 contract	6,806.65			
70 - Composition Shingles Replace										
BUILDING #8 - 5003				53,043	20	3	1 contract	53,043.44		
71 - Built-Up Roofing Replace			6,608	25	1	1 contract	6,608.40			
72 - Composition Shingles Replace										
ROOFING SYSTEM - ALL BUILDINGS:										
ROOFING SYSTEM:										
73 - Chimney Caps Replace			20,188	20	1	49 locations	412.00			
74 - Chimney Caps Replace			20,188	20	2	49 locations	412.00			
75 - Gutters & Downspouts Replace			2,575	2	1	1 fund	2,575.00			
76 - Spark Arrestors Replace			9,085	25	1	49 locations	185.40			
77 - Spark Arrestors Replace			9,085	25	2	49 locations	185.40			
ROOFING SYSTEM - GARAGES:										
78 - Composition Shingles Replace			51,936	25	12	9,600 square feet	5.41			
MISCELLANEOUS:										
79 Mailboxes Replace			10,397	10	5	98 structures	106.09			
CONSTRUCTION LOAN:										
80 - Amortization Payment Schedule			173,782	1	1	1 loan	173,782.00			

Accrued Liability

RESERVE COMPONENTS	Repair %	Current Repair/Replace Cost	Estimated Usd Life	Rmng Life	Annual Liability	Accrued Liability
BUILDING EXTERIORS:						
1 - Plywood Siding & Trim Paint	59,837	5	2	11,967	35,902	
2 - Plywood Siding & Trim Repair	47,689	5	2	9,538	28,614	
3 - Staircase Repairs	20,600	5	1	4,120	16,480	
4 - Stucco Siding Paint	144,155	10	2	14,416	115,324	
5 - Stucco Siding Repair	42,597	10	2	4,260	34,077	
6 - Unit Deck Stacks Rebuild	219,493	20	20	10,975	0	
7 - Unit Deck Stacks Rebuild	219,493	20	1	10,975	208,518	
8 - Unit Deck Joist Repairs	28,922	5	1	5,784	23,138	
9 - Water Intrusion Contingency	79,825	20	1	3,991	75,834	
10 - Wing Wall Repairs	49,440	3	1	16,480	32,960	
11 - Wood Bridgeway Repairs	30,900	10	1	3,090	27,810	
BUILDING INTERIORS - CLUBHOUSE:						
12 - Concealed Decay Contingency	21,000	15	1	1,400	19,600	
13 - Walls & Ceilings Paint	3,754	7	2	536	2,681	
14 - Deck Railings Repair	4,297	15	15	286	0	
15 - Deck Structure Rebuild	29,080	25	25	1,160	0	
FENCING & WALLS:						
16 - Chain Link Repairs - Tennis Cour	20%	1,680	15	5	112	1,120
17 - Retaining Walls Repair	25%	2,387	5	3	477	955
18 - Wood Gates Paint & Repair		2,864	5	2	573	1,719
19 - Wrought Iron Paint		1,650	5	2	330	990
20 - Wrought Iron Repair	10%	3,590	10	6	359	1,436
FLOOR COVERINGS:						
21 - Recreation Room Carpet Replace	2,507	7	1	358	2,149	
22 - Wood & Tile Floor Refinish	3,021	7	1	432	2,589	
FURNISHINGS & APPLIANCES:						
23 - Recitation Room Items	2,652	10	1	265	2,387	
LANDSCAPING:						
24 - Irrigation Timer Replace	1,167	5	3	233	467	
25 - Irrigation Valves	1,326	2	1	663	663	
26 - Major Tree Maintenance	5,305	3	1	1,768	3,536	
LIGHT FIXTURES:						
27 - Garage Lights Replace	3,437	20	5	172	2,578	
28 - Building Lights Interior	424	25	10	17	255	
29 - Exit Lights Replace	191	25	5	8	153	
30 - Ground Lights Replace	3,151	20	5	158	2,363	

Accrued Liability

RESERVE COMPONENTS	Assumed Annual Inflation Rate.....	3.0%	Repair %	Current Repair/Replace Cost	Estimated Usfl Life	Rmng Life	Annual Liability	Accrued Liability
LIGHT FIXTURES - CONTINUED:								
31 - Pole Lights - Fixture Replace			6,684	20	5	334	5,013	
32 - Unit Entry Lights Replace			9,877	20	5	494	7,408	
33 - Unit Patio & Deck Lights Replace			5,644	20	5	282	4,233	
34 - Walkway Lights Replace			5,952	20	5	298	4,464	
MECHANICAL SYSTEMS - GARAGE DOORS:								
35 - Garage Doors Replace - Doubles			40,314	20	5	2,016	30,236	
36 - Garage Doors Replace - Singles			1,008	20	5	50	756	
MECHANICAL SYSTEMS-HVAC:								
37 - Forced Air Furnace Replace			1,591	20	10	80	796	
MECHANICAL SYSTEMS-WATER:								
38 - Circulation Pumps Replace			1,500	10	3	150	1,050	
39 - Boilers Replace			12,000	15	8	800	5,600	
40 - Circulation Pumps Replace			3,000	10	4	300	1,800	
41 - Boilers Replace			24,000	15	9	1,600	9,600	
42 - Circulation Pumps Replace			7,500	10	5	750	3,750	
43 - Boilers Replace			60,000	15	10	4,000	20,000	
44 - Water Valve Replacements (2)			3,183	30	1	106	3,077	
45 - Water Valve Replacements (2)			3,183	30	2	106	2,971	
46 - Water Valve Replacements (2)			3,183	30	3	106	2,864	
47 - Water Valve Replacements (2)			3,183	30	4	106	2,758	
48 - Water Valve Replacements (1)			1,591	30	5	53	1,326	
PAVED SURFACES:								
49 - Asphalt Major Repair	33%		89,752	25	12	3,590	46,671	
50 - Asphalt Minor Repair	20%		27,197	10	7	2,720	8,159	
51 - Asphalt Sealcoat & Stripe			10,905	5	2	2,181	6,543	
52 - Concrete Walkway Repairs			1,591	5	2	318	955	
53 - Tennis Court Colorecat			8,784	7	2	1,255	6,274	
54 - Tennis Court Resurfacing			17,208	21	9	819	9,833	
RECREATION FACILITIES:								
55 - Tennis Court Net Replace			451	5	3	90	180	
56 - Tot Lot Fixtures			4,244	20	5	212	3,183	
ROOFING SYSTEM:								
BUILDING H - 5015			36,075	20	12	1,804	14,430	
57 - Built-Up Roofing Replace			6,807	25	17	272	2,178	
58 - Composition Shingles Replace								

Accrued Liability

RESERVE COMPONENTS	Assumed Annual Inflation Rate.....	3.0%	Repair %	Current Repair/Replace Cost	Estimated Usfl Life	Rmng Life	Annual Liability	Accrued Liability
BUILDING #2 - 5011								
59 - Built-Up Roofing Replace	36,075	20	12	1,804	272	272	14,430	14,430
60 - Composition Shingles Replace	6,807	25	17				2,178	2,178
BUILDING #3 - 5009								
61 - Built-Up Roofing Replace	36,075	20	12	1,804	272	272	14,430	14,430
62 - Composition Shingles Replace	6,807	25	17				2,178	2,178
BUILDING #4 - 5007								
63 - Built-Up Roofing Replace	36,075	20	12	1,804	272	272	14,430	14,430
64 - Composition Shingles Replace	6,807	25	17				2,178	2,178
BUILDING #5 - 5005								
65 - Built-Up Roofing Replace	36,075	20	12	1,804	272	272	14,430	14,430
66 - Composition Shingles Replace	6,807	25	17				2,178	2,178
BUILDING #6 - 5017								
67 - Built-Up Roofing Replace	36,075	20	12	1,804	272	272	14,430	14,430
68 - Composition Shingles Replace	6,807	25	17				2,178	2,178
BUILDING #7 - 5001								
69 - Built-Up Roofing Replace	36,075	20	12	1,804	272	272	14,430	14,430
70 - Composition Shingles Replace	6,807	25	17				2,178	2,178
BUILDING #8 - 5003								
71 - Built-Up Roofing Replace	53,043	20	3	2,652	264	264	45,087	45,087
72 - Composition Shingles Replace	6,608	25	1				6,344	6,344
ROOFING SYSTEM - ALL BUILDINGS:								
ROOFING SYSTEM:								
73 - Chimney Caps Replace	20,188	20	1	1,009	19,179	19,179		
74 - Chimney Caps Replace	20,188	20	2	1,009	18,169	18,169		
75 - Gutters & Downspouts Replace	2,575	2	1	1,288	1,288	1,288		
76 - Spark Arrestors Replace	9,085	25	1	363	363	363	8,721	8,721
77 - Spark Arrestors Replace	9,085	25	2	363	363	363	8,358	8,358
ROOFING SYSTEM - GARAGES:								
78 - Composition Shingles Replace	51,936	25	12	2,077	27,007	27,007		
MISCELLANEOUS:								
79 - Mailboxes Replace	10,397	10	5	1,040	5,198	5,198		
CONSTRUCTION LOAN:								
80 - Amortization Payment Schedule	173,782	1	1	173,782	0	0		
UNSCHEDULED.....								
					326,101	326,101	1,089,406	1,089,406
					2,046,939	2,046,939		